



Select a Category

GO

INSULATED TOOLS

[Product Index](#) > [Insulated Tools](#) > [33532-INS](#)

2-Piece Cushion-Grip Insulated Screwdriver Set

- Individually tested to exceed standards.
- Patented Tip-Ident® quickly identifies the type of screwdriver and tip orientation.
- Custom US-made tool steel.
- Cushion-Grip handles for greater torque and comfort.
- Includes one insulated keystone-tip screwdriver and one insulated Phillips-tip screwdriver.



Pictured: 33532-INS

Line Art: 33532-INS

| Cat. No. | Description | Overall Length | Weight (lbs.) |
|-----------|---------------------------------------|------------------|---------------|
| 33532-INS | Set Contains: 602-4-INS, 603-4-INS | 8-5/16" (211) | .60 |

All dimensions are in inches and (millimeters) except where indicated.

[Download High-Resolution .jpg photo](#)

[Download High-Resolution .jpg lineart](#)

[Download High-Resolution .eps photo](#)

[Download High-Resolution .eps lineart](#)



The downloadable files are compressed in .zip format to save on downloading times. Decompressing .zip files requires applications such as [WinZip](#) for the PC and [Stuffit Expander](#) for the Macintosh.

⚠ WARNINGS: Only use tools that are marked with the official international 1000-volt rating symbol shown above, if there is any chance that the tools will make contact with an energized source.

⚠ WARNINGS: Whenever possible, always de-energize lines and equipment prior to working on or around them. Klein insulated tools are designed only to reduce the chance of injury where the tool may make contact with an energized source.

⚠ WARNINGS: Do NOT touch uninsulated portion of the tool or any conductive object when either might contact an energized source.

⚠ WARNINGS: Wear approved eye protection. Always inspect your tools before use. Do not use if orange coating cracks, breaks or becomes damaged. Destroy tool if white layer shows through orange layer.

⚠ WARNINGS: Because moisture, films, or other surface contaminants are conductive, Klein insulated tools must be kept clean, dry, and free of any surface contaminants.