



SERVICE PARTS LIST

**BULLETIN NO.
54-04-2400**

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
Li-Ion Battery Charger				Sept. 2007
CATALOG NO.	48-59-2401	SERIAL NUMBER	B31A	
			WIRING INSTRUCTION	

EXAMPLE:


00	0
----	---

Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	12-20-2401	Service Nameplate	(1)

FIG. NOTES

- 1 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.





SERVICE PARTS LIST

**BULLETIN NO.
54-04-2400**

SPECIFY CATALOG NO. AND SERIAL NO. WHEN ORDERING PARTS			REVISED BULLETIN	DATE
Li-Ion Battery Charger				Sept. 2007
CATALOG NO.	48-59-2401	SERIAL NUMBER	WIRING INSTRUCTION	
		B31A		

EXAMPLE:

00	0
----	---

Component Parts (Small #)
Are Included When Ordering
The Assembly (Large #).

FIG.	PART NO.	DESCRIPTION OF PART	NO. REQ.
1	12-20-2401	Service Nameplate	(1)

FIG. NOTES

- 1 A clean, dry surface is essential for proper performance for any adhesive system. The area intended for application of any adhesive label or nameplate must be prepared by cleaning with isopropyl alcohol. The solvent is to be applied with a clean, lint free applicator and the surface allowed to dry before applying the label or nameplate.

